



FIG. 1



Communication slots/bypass holes on the outer sidewall/band. (Shown with impingement plates and other hardware)



View of post impingement region (44) of inner sidewall through to cavity 3 bypass and entrances (46).